Ver. 16/09/2019



USER INSTRUCTIONS

CLEANOR 138L

ELECTROLYTIC DEGREASER FOR GALVANIC

Colour : — Use : Bath Colour coordinates : L: — a: — b: —

Product description

CLEEANOR 138 L is an electrolytic degreaser concentrated for industrial uses for metal surfaces such as copper and steel.

Operating conditions

Parameter	Average suggested value	
Treatment time	120 seconds	
Temperature	40 °C	
Voltage	6.0 V	
Current density	6.0 A/dm²	
Cathodic efficiency	_	
Deposition speed	_	
Anodes	Stainless Steel	
Agitation	Moderate	
Ventilation	Necessary	

Maintenance of plating bath

The degreasing consumption is strictly related to the quantity of articles you have cleaned. Normally we suggest to change the solution when is dirty with deposition on the bottom or when the current displayed on the rectifiers is the 30% less then initially with the same working voltage.

Safety Information

Please refer to the safety data sheets for any information regarding safety and disposal (\mbox{MSDS}).



USER INSTRUCTIONS

CLEANOR 138L

ELECTROLYTIC DEGREASERS FOR GALVANIC

Colour : —	Use:—	Colour coordinates: L: —	a: —	b: —

Preparation of the galvanic bath

In order to prepare 1 L of ready to use solution is necessary following the right steps:

- 1. Arrange the working tank switching on the ventilation and all the safety devices.
- 2. Add 500 ml of water
- 3. Under agitation add 100 ml of CLEANOR 138L and mix
- 4. Fill up to 1 L with tap water.
- 5. Set the right working temperature

Wait till the working temperature and start with plating operation

Related products

Cod.Articles	Description	Colour	Packaging
SG010530	CLEANOR 138L Sgrassatura elettrolitica industriale concentrata	-	25 L